USB-C ports on MacBooks are soldered to ***macbook cleaning service nairobi*** the board or sit on a small sub-board depending on model. A worn port that only charges at one angle needs replacement rather than a new cable. Port notes macbook repair nairobi macbook repair nairobi macbook repair services in nairobi kenya macbook screen repair nairobi macbook battery replacement nairobi macbook pro repair nairobi macbook air repair nairobi at %LINK%.