

- Air leaking around the edges or at the bottom
- Hardware problems caused by misalignment or wear
- A failed insulated glass seal
- Poor solar control and weak insulation
- Drainage or flashing problems that need correction

If the opening faces afternoon sun, sits near a pool, or opens to a room you use all day, the upgrade [Rowlett Windows & Doors 214-319-8832](tel:214-319-8832) tends to feel more valuable right away. They help the room feel calmer, the AC cycle less aggressively, and the entire space more usable during the worst months.